



# FASTENERS



## BOLTS




## NUTS




## SCREWS



TAPPING SCREW TYPES



MACHINE & SET SCREW POINTS



-HEAD STYLES-  
DRIVER



ABOVE SCREWS IN ALLOY & STAINLESS STEEL